
DEPARTMENT OF CIVIL AVIATION
Airworthiness Notices

A/26

**AIRCRAFT PARTS AND MATERIALS USED FOR THE MAINTENANCE OF
AIRCRAFT REGISTERED IN MYANMAR**

1. The attention of all concerned is drawn to the fact that cases have occurred where defective parts have been replaced by parts manufactured without reference to drawings, the defective parts being used as a pattern.
2. In circumstances such as those referred in paragraph 1, there is considerable risk of the new part being made to incorrect dimensions and/or of incorrect materials.
3. In every case where it is necessary to manufacture any aircraft part for the aircraft for which a certificate of airworthiness has been issued or is to be issued or renewed, such aircraft part must be manufactured and inspected by the organization approved for that manufacturing by the state of design of that type of aircraft and must be installed in accordance with approved drawings.
4. Certification of any repair or replacement under the requirements of the Myanmar Civil Aviation Requirements shall not be made unless either:
 - (a) the replacement parts have been approved by the manufacturers of the aircraft; or
 - (b) the parts have been manufactured and inspected as specified in paragraph 3 of this notice; or
 - (c) the repair has been approved as a modification subsequent to the issue of a certificate of airworthiness.
5. The existence of an inspection stamp is not in itself sufficient evidence of approval of parts and materials, approved certificates are also required, and these documents should be available for examination when an aircraft is inspected for the issue or renewal of a certificate of airworthiness or as required by the Department of Civil Aviation.